

SECRET

Approved For Release 2002/08/19 : CIA-RDP81B00878R000700030259-1

APPENDIX A

Roll #168, PTF 85 dated 13 February 1956

LO Camera A-1

1. Negatives thin, however only primary processing utilized. Negatives would have been of better quality if secondary development and fix would have been used.
2. Clock image present but unreadable.
3. Pressure striations paralleled to film travel and present throughout entire roll.

Roll #191, PTF 98 23 February 1956

RO Camera A-1

1. Clock recorded but illegible.
2. Considerable evidence of flare light, although horizon indicates very little change in a/c attitude.
3. During course of pre-flight check on flight line objects of a classified nature were recorded.

Roll #193, PTF 98 23 February 1956

LO Camera A-1

1. No clock.
2. Marked evidence of unequal tension on rollers and foreign particles on rollers and platen.

NOTE: The vertical photos of PTF 98 were retained at Site for pilot evaluation. Our records show however that the vertical camera shutter hung up every 3 or 4 exposures.

Roll 190 and 194, PTF 97 and 98 21 February 1956

Rocker Camera A-1

1. No clock.
2. Negatives dense. May be due in part to reflections from thin layered undercast.

Roll 209, PTF 105 29 February 1956

Rocker Camera A-1. A-25 filter utilized.

Filter Factor 7

1. Extremely under exposed.
2. Metering trouble.
3. No clock.
4. Formats askew.

Approved For Release 2002/08/19 : **SECRET** 81B00878R000700030259-1